



# GA

## General Aluminum spacer code location help.

Locate code between  
glass panes on the  
metal spacer

Use these guidelines to determine the Stenciled Code

ASTM X### CLASS X XX-# XX

X= To a letter

#= To a number.

This Alpha Numeric Code is important and must be included on all warranty item request. It must come from the window or door glass pane in question.